



DJI P1 Release Notes

Release Date:	2025.06.10	
DJI P1 Firmware:	v10.01.02.01	
Firmware Upgrade Method:	SD card	
Other Product Firmware and Software Required:		
M350 RTK Aircraft:	v14.01.00.06	
DJI RC Plus Remote Controller:	v05.02.13.04	
DJI Pilot 2 App:	v13.0.4.1	
M300 RTK Aircraft:	v64.01.00.04 (for DJI RC Plus)	v10.01.08.01 (for DJI Smart Controller Enterprise)
M300 RTK Remote Controller:	v05.02.13.04 (DJI RC Plus)	v10.01.08.01 (DJI Smart Controller Enterprise)
DJI Pilot 2 App:	v13.0.4.1 (built-in DJI RC Plus)	v10.1.8.14 (built-in DJI Smart Controller Enterprise)

What's New?

- Added support for Matrice 400.
- Fixed some known issues.

Notes

- After updating to the latest firmware version, the user cannot downgrade to v03.00.01.04 or earlier.
- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.



DJI P1 Release Notes

Release Date:	2023.04.26
DJI P1 Firmware:	v07.00.01.10
Firmware Upgrade Method:	DJI P1 - SD card / Update All in App
Other Product Firmware and Software Required:	M300 RTK aircraft firmware: v06.01.01.00 M300 RTK remote controller firmware: v06.01.01.00 DJI Pilot App 2 Android: v6.1.2.3

What's New?

- Fixed issue where the camera cannot stop taking photos when pressing the shutter button in Timed mode after frequently switching between Timed mode and Video mode.

Notes

- After updating to the latest firmware version, the user cannot downgrade to v03.00.01.04 or earlier.
- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.



DJI P1 Release Notes

Release Date:	2022.09.28
DJI P1 Firmware:	v04.00.02.05
Firmware Upgrade Method:	DJI P1 - SD card / Update All in App
Other Product Firmware and Software Required:	M300 RTK aircraft firmware: v04.01.00.00 M300 RTK remote controller firmware: v04.01.01.01 DJI Pilot App Android: v4.1.1.14 (M300)

What's New?

- Added support time synchronization and position compensation when using with the DJI DL 24mm/50mm F2.8 LS ASPH Lens.
- Fixed issue: HMS prompts lens infinity focus is not calibrated after Infinity Focus Calibration is performed by the user.
- Fixed issue: the AWB difference is too large in some scenarios.

Notes

- After updating to the latest firmware version, the user cannot downgrade to v03.00.01.04 or earlier.
- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.



DJI P1 Release Notes

Release Date:	2021.10.22
DJI P1 Firmware:	v03.00.01.04
Firmware Upgrade Method:	DJI P1 - SD card / Update All in App
Other Product Firmware and Software Required:	M300 RTK aircraft firmware: v03.00.01.01 M300 RTK remote controller firmware: v03.00.01.02 DJI Pilot App Android: v3.0.1.4 (M300)

What's New?

- Added 0.7s shooting interval to manual Timed Shot.
- Added support to transcode satellite observation files from binary format to Rinex format in real-time.
- Fixed issue: when a new folder was created, the PPK data for the last 10 seconds of the old folder was incorrectly stored to the new folder.
- Fixed issue: could not record MRK and PPK files when taking photos in DNG format.
- Fixed issue: could not record exact location and time stamp when taking photos in DNG format.
- Fixed occasional issue: shots missed during Smart Oblique flight.

Notes

- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.

DJI P1 Release Notes

Release Date:	2021.05.10
DJI P1 Firmware:	v02.04.01.02
Firmware Upgrade Method:	DJI P1 - SD card / Update All in App
Other Product Firmware and Software Required:	M300 RTK aircraft firmware: v02.04.01.02 M300 RTK remote controller firmware: v02.04.01.03 DJI Pilot App Android: v2.4.1.7 (M300)

What's New?

- Added lens activation. Activation will be triggered after firmware is updated.
- Added one second timed shot in DJI Pilot when taking photos manually.
- Added Oblique GSD in DJI Pilot.
- Optimized resumption of interrupted flight route tasks in Smart Oblique. Aircraft will return to break point and adjust to flight speed and complete shooting sequence of previous waypoint.
- Optimized camera exposure compensation to improve exposure accuracy of entire flight route.
- Improved calculation accuracy of frontal overlap ratio in Smart Oblique.
- Optimized estimation of photo numbers and flight time in Smart Oblique.
- Fixed issue: white spots appeared in corners of DNG photos.
- Fixed some minor bugs.

Notes

- Follow steps to activate lens when prompted in DJI Pilot.
- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.



DJI P1 Release Notes

Release Date:	2021.03.11
DJI P1 Firmware:	v02.02.03.02
Firmware Upgrade Method:	DJI P1 - SD card / Update All in App
Other Product Firmware and Software Required:	M300 RTK aircraft firmware: v02.02.02.01 M300 RTK remote controller firmware: v02.02.01.02 DJI Pilot App Android: v2.2.1.7

What's New?

- Reduced motion blurring that occasionally occurred when shooting some photos in Smart Oblique.
- Reduced screen blurring and freezing during video transmission in Smart Oblique.
- Fixed occasional issue: false gimbal overload warning prompt was sent.

Notes

- Make sure that the aircraft firmware, remote controller firmware, DJI P1 firmware, and DJI Pilot app firmware are updated to the latest.